

MUST-SEE SOLUTIONS

Intake Manifold and Valve Cover Kit

NEW CONVENIENT SOLUTION

PACKAGES **THREE RELATED REPAIRS TOGETHER** TO GET THE JOB DONE RIGHT THE FIRST TIME.



615-380KIT

1.4L Ecotec engines;
Buick 2019-13, Chevrolet 2019-12

VIO: 1.634.899



PROBLEM:

The valve in the intake manifold often becomes dislodged, causing excessive vacuum that then damages the diaphragm integrated into the valve cover's PCV cap.



FIX:

A complete repair of all damaged components, with a redesigned, OE FIX manifold to prevent future intake manifold and valve cover failure. It also includes a PCV tube assembly, because this part frequently breaks during removal.



Engine Valve Cover

RELIABLE REPLACEMENT
OVER 50 SKUS NOW AVAILABLE



264-920

Chevrolet 2018-08, Pontiac 2010-09,
Saturn 2009-08, 1.8L and 3.2L engine

VIO: 735.336

Direct replacement valve cover matches the fit and function of the original equipment part that may be damaged or warped

- Made of quality materials to withstand extreme temperatures to resist leaking
- Installation hardware included for a complete repair solution

Sliding Door Handle Repair Kit

TIME & MONEY SAVER



926-288

Chrysler Town & Country 2016-08,
Dodge Grand Caravan 2019-08

VIO: 2.250.638

PROBLEM:

The sheet metal fatigues behind the door handles on certain minivans, leaving the handle unsecured without extensive repair to the door panel.

FIX:

This door handle repair kit allows the damaged door panel to be repaired in place with no cutting or welding to securely restore the handle's function.



A/C Hose Assembly

IMPROVED DESIGN & TIME SAVER



926-999

Chevrolet Trailblazer EXT 2006-02, GMC Envoy XL 2006-02

VIO: 301.778

PROBLEM:

The factory aluminum A/C lines corrode with exposure to the elements, causing the air conditioning system to fail.

FIX:

These time-saving Dorman OE FIX A/C lines are made of flexible reinforced rubber to simplify installation under the vehicle.



Nitrogen Oxide (NOx) Sensor

LINE EXTENSION



904-421

Chevrolet Express and Silverado 2014-10, GMC Savana and Sierra 2014-10, 6.6L Downstream Sensor

VIO: 263.885

Direct replacement NOx sensor matches the function and performance of the original sensor on specified vehicles

- Properly repairs nitrogen oxide detection to comply with emissions regulations

FAIL MODE & SIGN:

- Original sensor fails due to debris and contamination, resulting in illumination of the check engine light and vehicle going into engine derate



MUST-SEE SOLUTIONS

Accelerator Pedal Sensors

LINE EXTENSION | **OVER 15 SKUS NOW AVAILABLE**



699-199

Acura 2008-03, Honda 2014-03

VIO: 3,055,749

Direct replacement accelerator pedal position sensor matches the fit and performance of a failed original equipment sensor to restore proper vehicle operation

- Plug and play installation - no special tools or programming required to install this sensor

Radiator Shutter Assemblies

FIRST-TO-AFTERMARKET
OVER 10 SKUS NOW AVAILABLE



601-332

Subaru Legacy 2017-15, Subaru Outback 2017-15

VIO: 712,554

Matches the fit and function of the original equipment shutter to restore function to the vehicle's active grille shutter system


- Plug and play installation - this grille shutter assembly is made with a factory-style electrical connector for a trouble-free installation
- Mounting bracket included for a complete repair solution

FAIL MODE & SIGN:

- Broken grille shutters or motor failure, illumination of the check engine light or high engine temperatures

Adaptive Light Module

FIRST-TO-AFTERMARKET



601-318

BMW 2015-06

VIO: 820,037

Matches the fit and function of the original equipment module to restore proper directional control to an adaptive headlight

- Durable construction features a new housing and seal to prevent damage from moisture intrusion

FAIL MODE & SIGN:

- Water intrusion in the head light will lead to shorts in the module's circuit board, causing error light to display

Intercooler

LINE EXTENSION



904-963

Buick Verano 2016-13, Chevrolet Cruze 2016-11, Chevrolet Cruze Limited 2016

VIO: 1,079,054

Direct replacement for an original equipment intercooler that has failed from oil contamination or leaks

- Durable construction is made from corrosion-resistant aluminum
- Has undergone dimensional, corrosion and flow testing to ensure proper fit and performance

FAIL MODE & SIGN:

- Clogged or corroded tube causes engine power loss or increased fuel consumption

PCV Valve Tube

FIRST-TO-AFTERMARKET
OVER 30 SKUS NOW AVAILABLE



46831

Ford 2004-02, Lincoln 2004-02

VIO: 1,158,294

Made from quality materials to resist cracking and brittleness, this PCV hose replaces a worn or leaking original equipment hose

- Designed to withstand exposure to extreme temperatures and oil vapors

FAIL MODE & SIGN:

- Breakage from age, wear and tear or removal leads to rough idle, oil consumption and illumination of the check engine light

Sun Visor

FIRST-TO-AFTERMARKET



74207

Hyundai Accent 2011-07

VIO: 169,947

Damaged, worn or missing sun visor? Don't go back to the dealership! Dorman continues to release new, exclusive, direct replacements.

- Matches the original sun visor in style, color and texture to blend seamlessly with overall interior

FAIL MODE & SIGN:

- Sagging, broken detent mechanism or separating at seams

