


Steering Shafts

AFTERMARKET EXCLUSIVES | **NOW 100+ PARTS AVAILABLE**



425-130

Cadillac Escalade 2006-02, Chevrolet Silverado, Suburban, Tahoe 2013-99, GMC Yukon, Sierra 2013-99

425-131

Chevrolet Silverado 2010-01, GMC Sierra 2010-01

ALSO NOW AVAILABLE:

425-132

Chevrolet Silverado 2007-99, GMC Sierra 2007-99

If you think you can only get quality replacement steering shafts from the dealership, think again. Dorman has heavily invested in our steering shaft program, and these three new steering shafts fit more than 10 million General Motors vehicles.

- Every design meets rigorous Federal Motor Vehicle Safety Standards
- Engineered in the USA to precise specifications to ensure a secure fit

Air Suspension Compressors

UPGRADED REPLACEMENTS



949-356

Ram 1500 2018-13

949-356XD

Ram 1500 2018-13

PROBLEM:

The compressor on certain Ram nitrogen-filled suspension systems often fails from moisture intrusion and/or when the plastic piston wears, and until now there was no aftermarket replacement.

FIX:

Dorman's exclusive OE FIX compressor features an aluminum piston, improved seals and upgraded thermal classification - all features the OE doesn't even offer. Dorman also delivers an even more rugged replacement, with a version for the same vehicles that features a vented cast aluminum housing to prevent damage to the compressor in extreme road conditions.

Windshield Wiper Motor and Linkage Assemblies

AFTERMARKET EXCLUSIVES



602-230AS

Cadillac Escalade 2014-07, Chevrolet Silverado, Suburban, Tahoe 2014-07, GMC Yukon, Sierra 2014-07

Ever replace a customer's wiper motor, only for the transmission to fail soon after? Or vice versa?

Avoid a comeback with Dorman's new line of complete wiper motor and transmission assemblies. They are 100% newly manufactured, and by replacing both related components together you cut total labor time by up to 35% compared to replacing them separately.

ALSO NOW AVAILABLE:

602-118AS
Dodge 2010-05

602-231AS
Chevrolet Cruze 2015-10, Chevrolet Cruze Limited 2016

602-309AS
Ford 2004-97, Lincoln 2003-98

602-508AS
Honda Accord 2007-03

602-117AS
Dodge Ram 1500 2001-97, Dodge Ram 2500 2002-97, Dodge Ram 3500 2002-97

Active Grille Shutter

LINE EXTENSION | **NOW 17 PARTS AVAILABLE**



601-326
Ram 1500 2017-13

This radiator shutter assembly matches the fit and function of the original equipment shutter to restore function to the vehicle's active grille shutter system.

- Includes motor for complete repair

Hood Latch

AFTERMARKET EXCLUSIVE



820-899
Chrysler 2010-02, Dodge 2011-97,
Mitsubishi 2009-06, Ram 2011

This replacement hood latch assembly matches the fit and function of the original equipment hood latch and is made of corrosion-resistant materials for reliable service.

NOx Sensor

LINE EXTENSION | **NOW 18 PARTS AVAILABLE**




904-6035
Dodge 2012-11, Ram 2012-11

This NOx sensor has been made to match the original equipment sensor on certain vehicle years, makes and models, properly restoring nitrogen oxide detection to comply with emissions regulations.

Preformed Fuel Line



UPGRADED REPLACEMENT
NOW 18 OE FIX FUEL LINES AVAILABLE



919-844
Chevrolet 2007-04, GMC 2007-04

PROBLEM:
The original fuel line often fails when the protective rubber coating deteriorates and allows the steel line to corrode.

FIX:
This Dorman OE FIX fuel line is made from corrosion-resistant stainless steel for greater durability.

Flow Sensor

AFTERMARKET EXCLUSIVE
COST SAVER



926-818
Lexus 2018-10, Toyota 2018-10

PROBLEM:
When the original equipment A/C compressor flow sensor fails, the dealer requires the entire air conditioning compressor to be replaced.

FIX:
This money-saving Dorman OE FIX solution allows only the failed sensor to be replaced.

Air Compressor Valve Block

CONVENIENT REPLACEMENT



949-302
Jeep Grand Cherokee 2019-11

This air compressor solenoid valve unit, also known as an air compressor valve block, directly replaces the original unit on specific vehicles. Replacement allows for proper regulation of nitrogen in the suspension.

Throttle Body Unit

UPGRADED REPLACEMENT
NOW 12 OE FIX THROTTLE BODIES AVAILABLE




977-021
Chevrolet 2006-04, Pontiac 2006-05,
Saturn 2007-02

PROBLEM:
Original equipment throttle bodies often fail when moisture and oil intrusion foul the internal electronics.

FIX:
This Dorman OE FIX throttle body features a proprietary shaft seal to prevent future failures from this contamination.

Gearshift Control Cable

AFTERMARKET EXCLUSIVE



905-609
Ford F-150 2004

This automatic transmission shifter cable matches the fit and function of the original equipment cable to ensure a trustworthy repair. Made of quality materials, it has been extensively tested to ensure a long service life.